

คำอธิบายสัญลักษณ์และคำย่อ

BLX	=	Blend Crossover Operator
CFR	=	Concentric Fiber Ring
E	=	Modulus of elasticity
FEM	=	Finite Element Method
FFD	=	Full Factorial Design
GA	=	Genetic Algorithm
NSGA-II	=	Non-Dominated Sorting Genetic Algorithm
ε	=	Material Strain
σ	=	Material Stress
σ_f	=	Fracture Stress
σ_u	=	Ultimate Stress
σ_{pl}	=	Proportional limit
σ_y	=	Yield Stress or elastic limit
ν	=	Poisson's ratio